Truckers Guide

South Carolina Ports
INLAND PORT

TERMINAL REQUIREMENTS:

- CDL or TWIC
- DRIVER MUST HAVE **GATE CODE** FOR ALL MISSIONS
- SAFETY VEST MUST BE WORN
- FRONT LICENSE PLATE MUST BE UNOBSTRUCTED (NO COVERS, SHIELDS, ETC.)
- CELLULAR PHONES AND OTHER ELECTRONIC DEVICES CANNOT BE USED WHILE TRAVELING

---

1. After passing through the Security Gate, drive thru the AGS Inbound Portal. (Terminal Speed Limit is **25 mph**, AGS Portal Speed Limit is **12 mph**)

2. Proceed to the Inbound Inspection canopy. Lift card reader cover and place CDL or TWIC on scanner (**CDL/TWIC must be removed from case or protective covering before placed on scanner**). Once completed, follow instructions displayed on the Kiosk's screen. Use keypad located on Kiosk to enter information.

3. You will be issued a "**Routing Slip**" that explains what you are to do for your mission.

ICON MEANINGS

Icon	Meaning
→	Direction of Movement
PF020	Container Stack with Location
CD036	Wheeled Row with Location
MOSK 41028	Bare Chassis
MOLU216438	Married Container & Chassis
EXIT	Leave Terminal After Gate Out
(!)	Follow Given Instructions

Routing Slip example:

Receive Loaded Container — Apr 29, 1999 3:09 PM
Job Number 0809 | ORION Number 976730 | Tractor 3150
Shipping Line (55555) BEST SHIPPING LINE
Trucking Company (BT) BEST TRUCKING CO.
Seal 009223 | Seal (add)
DRY 40'/8'6"
FMCU 201358 → DE020
CHAZ 304930 → EK017
EXIT

Section: D Row: E Slot: 020

Section: E Row: K Slot: 017A

Communication from Container Handler

- 1 horn beep – pull forward
- 2 horn beeps – back up
- 1 horn beep while moving – Stop

---

4. After completing all tasks on the "**Routing Slip**," drive through the AGS Outbound Portal and proceed to the outbound lane Kiosk.

5. Follow the instructions on the Kiosk's screen. Use keypad to enter required information.

6. Present your Carrier Interchange to Guard Gate.

Driver Assistance Telephone Numbers

Voice: (864) 968-7901
Fax: (864) 877-2041

P GO! RT   GOPORT.SCSPA.COM